

## PHONE MEMO

230820



**Contact:** Ben Alter

**Phone #:** 973-256-7800

**Of:** GZA GeoEnvironmental, Inc.

**Date:** 10/15/04

**Case Name:** Unimatic Manufacturing Co.

**Case #:** E20010335

---

**RE:** PCBs that remain in the ground after excavation

---

I spoke with Ben Alter regarding the status of the remaining areas that contain PCBs greater than 100-mg/kg, post excavation that area depicted in the Jan. '04 Supplemental RIR.

- There are two remaining areas:

1. Under the building
2. SB-84, where ground water monitoring well MW-6 is proposed on the proposed monitoring well location map, received 9/22/04.

1. Soils > 100-mg/kg remain under the building, at the time the borings were installed the building was empty. Currently, the building is occupied and is filled with shelving. I will be on-site this coming Wed., Oct. 20 to photograph the site and building interior. I'll meet Ben on-site.

2. Soils > 100-mg/kg remain at SB-84 that are too far below the water table to excavate. However, the vertical depth is delineated.